

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicant: Daniel Nelson) I hereby certify that this paper is) being deposited with the United) States Postal Service with
Serial No.: 10/047,734) sufficient postage via first class) mail in an envelope addressed to
Filed: November 9, 2001	 Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313- 1450 on this date
For: APPARATUS AND METHOD FOR DETECTING AND CORRECTING A CORRUPTED BROADCAST TIME CODE	February 6, 2006 Mark G. Hanley Registration No. 44, 736
Group Art Unit: 2133) Attorney for Applicant(s)
Examiner: F. Alphonse)

LETTER TO THE DRAFTSMAN

Commissioner for Patents P.O. Box 1450 Alexandria, Virginia 22313-1450

Sir:

Applicant is submitting attached to this paper a replacement drawing for FIG. 2 in above mentioned application. In the replacement drawing, the lead line for the temporary memory buffer 37 is extended from the box next to the memory device 35 instead of the processor 32. Applicant respectfully submits that this modification corrects an error in the drawing and does not add any new matter. Applicant respectfully requests entry of this replacement drawing.

Respectfully submitted,

HANLEY, FLIGHT, & ZIMMERMAN, LLC Suite 4220 20 North Wacker Drive Chicago, Illinois 60606 (312) 580-1588

By:

Mark G. Hanley

Registration No. 44, 736

February 6, 2006